#### DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

# WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-004846 Address: 333 Burma Road **Date Inspected:** 30-Nov-2008

City: Oakland, CA 94607

**OSM Arrival Time:** 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1730 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

**CWI Name: CWI Present:** Yes No Yes N/A **Rod Oven in Use:** Yes No **Inspected CWI report:** No N/A N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes No N/A **Approved Drawings:** Yes No **Approved WPS:** Yes No N/A **Delayed / Cancelled:** 

34-0006 **Bridge No: Component:** OBG

### **Summary of Items Observed:**

On this date, Caltrans Office of Structure Materials (OSM) Quality Assurance Inspector (QA) Raymond Lara was present at jobsite in Zhenhua Port Machinery Company facility on Changxing island, China for the purpose of observing and monitoring the fabrication of the SAS Superstructure.

## Outside Area West of the Bay Sub-Assembly

The Quality Assurance Inspector performed Ultrasonic Testing (UT), prescreening, on completed Partial Joint Penetration (PJP) groove welds, tack weld areas only, on Deck Panel DP554-001. The prescreening is in effort to determine the condition of said tack welds for compliance with project specifications. Numerous indications indicative of cracks were located.

#### **Summary of Conversations:**

No relevant conversations on this date.

## **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Peter Dautermann 150 0219 9593, who represents the Office of Structural Materials for your project.

Inspected By:	Lara, Raymond	Quality Assurance Inspector
Reviewed By:	Wright,Mark	QA Reviewer